



Service Bulletin

Date: January 8, 2009

Product Line: Snowmobile

Bulletin No: 2009-1-09

Subject: Torque Bracket Retainer

Affected Models: All 2009 models within the manufactured sequence range of 120006-127159.

■ **NOTE:** For identification purposes, it is necessary to refer to only the last six digits of the VIN. Also please refer to Cat Tracker to verify if a VIN is affected by this Service Bulletin.

Condition: It has been determined that the existing torque bracket retainer in the driven pulley on the affected models does not meet Arctic Cat standards and needs to be replaced.

Solution: Remove and discard the existing torque bracket retainer and all nine machine screws; then install new Torque Bracket Retainer and secure with nine new Machine Screws.

Parts: Order an appropriate number of Torque Bracket Retainer Update Kits (p/n 0637-322) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.5 hr will be paid per affected snowmobile.

■ **NOTE:** It is required to enter the current mileage of each affected model at the time the claim is submitted.

 **ATTENTION**

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to January 8, 2010. All warranty claims directly related to this issue will not be honored after January 8, 2010 without prior approval.



Bulletin de Service

Date: Le 8 janvier 2009

Ligne de produit : Montoneige

Numéro de bulletin : 2009-1-09

Objet : Retenue du Support de Torsion

Modèles concernés : Tout modèles 2009 entre la range de NIV de 120006-127159.

■ **REMARQUE:** A des fins d'identification, il est nécessaire de se référer seulement aux six derniers chiffres du NIV. SVP Verifier sur Cat Tracker si le numéro de série est affecté par ce bulletin.

Condition : On à déterminer que la retenue du support de torsion de la poulie menée sur les modèles affectés ne sont pas aux normes d 'Arctic Cat et doit être remplacer.

Solution : Enlever et jeter la retenue du support de torsion existante et les 9 vis de mécanique. Installer la nouvelle retenue du support de torsion et serrer avec les 9 vis de mécanique nouvelles.

Pièces : Commandez un nombre approprié des Trousses de retenue du Support de Torsion (n/p 0637-322) en passant par les voies de commande de pièces normales. Votre compte de pièces de concessionnaire sera facturé et ensuite crédité lors de la réception du Formulaire de demande de réclamation de garantie.

Main-d'oeuvre : Une allocation de main-d'oeuvre de 0,5 h sera payée par motoneige concernée.

■ **REMARQUE:** Veuillez vous rappeler que lorsque vous soumettez une réclamation, de vous assurer d'inscrire le millage actuel de chaque véhicule concerné.

ATTENTION

Pour s'assurer que le travail de révision nécessaire soit complété rapidement et que ce problème peut être réglé, Arctic Cat demande que tout travail de révision soit complété avant le 8 janvier 2010. Toutes réclamations de garantie directement en rapport à ce problème ne seront plus acceptées après le 8 janvier 2010 sans préautorisation.