



Product Safety Recall Bulletin

Date: June 25, 2008

Product Line: ATV

Subject: Carburetor

Bulletin No: 2009-2-01 (50 cc **Condition A**) (90 cc **Condition B**)
(California 90 cc **Condition C**)

Affected Models: All 2008 Arctic Cat 50 cc and 90 cc models

What is the reason for this notice?

In cooperation with the U.S. Consumer Product Safety Commission (CPSC), Arctic Cat is voluntarily recalling the ATV's identified above for necessary service work.

Immediately stop selling the affected ATV's until the necessary service work has been completed.

Condition A,B,C: On some of the affected ATV's, the speed controller valve alignment pin in the carburetor may not be properly seated and could move providing an opportunity for the slide valve to not return to the idle position. Operation of the vehicle can cause the throttle to not function properly which will then not return to the idle position. If this condition exists, loss of throttle control may occur resulting in possible bodily injury or death.

Solution A: Install Carburetor Kit (p/n 1436-294) for all 2008 DVX 50 and 50 Utility models according to the instructions included in the kit.

Solution B: Install Carburetor Kit (p/n 1436-293) for all 2008 DVX 90 and 90 Utility models according to the instructions included in the kit.

Solution C: Install Carburetor Kit (p/n 1436-296) for all 2008 California 90 cc models according to the instructions included in the kit.

WARNING

Do not operate or permit anyone to operate an affected vehicle until the appropriate carburetor has been replaced.

What should you do?

Please contact all customers who have taken possession of an affected vehicle. Be sure to complete the necessary service work before releasing any more affected vehicles to customers.

■ **NOTE:** Arctic Cat will also contact all registered owners concerning this issue.

Parts: Order an appropriate number of Carburetor kits for DVX 50 and 50 Utility models (p/n 1436-294), DVX 90 and 90 Utility models (p/n 1436-293), and California 90 cc models (p/n 1436-296) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.5 hr will be paid per affected ATV.



Product Safety Recall Bulletin

Date: June 25, 2008

Product Line: ATV

Subject: Carburetor

Bulletin No: 2009-2-01 (50 cc **Condition A**) (90 cc **Condition B**)

Affected Models: All 2008 Arctic Cat 50 cc and 90 cc models

What is the reason for this notice?

In cooperation with the Canadian Department of Transport, Arctic Cat is voluntarily recalling the ATV's identified above for necessary service work.

Immediately stop selling the affected ATV's until the necessary service work has been completed.

Condition A & B: On some of the affected ATV's, the speed controller valve alignment pin in the carburetor may not be properly seated and could move providing an opportunity for the slide valve to not return to the idle position. Operation of the vehicle can cause the throttle to not function properly which will then not return to the idle position. If this condition exists, loss of throttle control may occur resulting in possible bodily injury or death.

Solution A: Install Carburetor Kit (p/n 1436-294) for all 2008 DVX 50 and 50 Utility models according to the instructions included in the kit.

Solution B: Install Carburetor Kit (p/n 1436-293) for all 2008 DVX 90 and 90 Utility models according to the instructions included in the kit.

WARNING

Do not operate or permit anyone to operate an affected vehicle until the appropriate carburetor has been replaced.

What should you do?

Please contact all customers who have taken possession of an affected vehicle. Be sure to complete the necessary service work before releasing any more affected vehicles to customers.

■ **NOTE:** Arctic Cat will also contact all registered owners concerning this issue .

Parts: Order an appropriate number of Carburetor kits for DVX 50 and 50 Utility models (p/n 1436-294), DVX 90 and 90 Utility models (p/n 1436-293) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.5 hr will be paid per affected ATV.



Bulletin de rappel de sécurité du produit

Date : Le 25 juin 2008

Ligne de Produit : VTT

Objet : Carburateur

Numéro de bulletin : 2009-2-01 (50 cc Condition A) (90 cc Condition B)

Modèles Concernés : Tous les modèles 50 cc et 90 cc de 2008.

Quelle est la raison de cet avis ?

En collaboration avec le Département de Transport Canadien, Arctic Cat rappelle volontairement les VTT identifiés ci-haut en rubrique pour le travail de révision nécessaire.

Cessez immédiatement de vendre les VTT concernés jusqu'à ce que le travail de révision nécessaire ait été complété.

Condition A&B: Sur les VTT touchés, la goupille d'alignement de la soupape du contrôleur de vitesse dans le carburateur n'est peut-être pas correctement assujettie et pourrait par conséquent se déplacer et potentiellement empêcher la soupape de revenir à la position de ralenti. L'utilisation du véhicule pourrait alors causer un mauvais fonctionnement du papillon qui ne reviendrait pas à la position de ralenti. Si cette condition existe, une perte de contrôle du papillon peut survenir et potentiellement entraîner de blessures corporelles, voire même la mort.

Solution A: Installez la Trousse de carburateur (n/p 1436-294) pour tout modèles DVX 50 et 50 Utility de 2008 selon les instructions incluses dans la trousse.

Solution B: Installez la Trousse de carburateur (n/p 1436-293) pour tout modèles DVX 90 et 90 Utility de 2008 selon les instructions incluses dans la trousse.

AVERTISSEMENT

N'opérez pas ou ne permettez à qui que ce soit d'opérer un véhicule concerné jusqu'à ce que la pièce de quincaillerie appropriée ait été vérifiée et resserrée aux facteurs de torsion adéquats.

Que devriez-vous faire ?

Veuillez communiquer avec tous les clients qui ont pris possession d'un véhicule concernée. Assurez-vous de compléter le travail de révision nécessaire avant de laisser d'autres véhicules concernés aux clients. Voyez les instructions joignant ce bulletin.

■ **REMARQUE :** Arctic Cat communiquera également avec tous les propriétaires enregistrés concernant ce problème.

Pièces : Commandez une quantité adéquate de carburateurs pour les DVX 50, les 50 Utility (n/p 1436-294) les DVX 90, 90 Utility (n/p 1436-293) par le biais du réseau habituel de commande de pièces. Votre concessionnaire sera remboursé lors de la réception du formulaire de Demande de Réclamation de Garantie.

Garantie : Une allocation de main-d'oeuvre de 0,5 h sera payée par VTT concerné.