



Service Bulletin

Date: November 8, 2007

Product Line: UTV

Bulletin No: 2008-6-03

Subject: Gear Case Vent Hose Bladder

Affected Models:

All 2008 Prowler and Prowler XT Models within the VIN range of 4UF08MPV08T300001 – 4UF08MPVX8T305853

Condition: It has been determined that the existing gear case vent hose bladder does not meet Arctic Cat expectations and must be replaced.

Solution: Install Bladder/Loom Assembly Kit (p/n 1436-183) according to the instructions included in the kit.

Parts: Order an appropriate number of Bladder/Loom Assembly Kits (p/n 1436-183) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected vehicle.

■ **NOTE:** Please remember that when submitting a claim, make sure to enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to November 8, 2008. All warranty claims directly related to this issue will not be honored after November 8, 2008 without prior approval.

