



Service Bulletin

Date: March 17, 2009

Product Line: Snowmobile

Bulletin No: 2009-1-10

Subject: Foam Update Kit
(Sound Reduction)

Affected Models: All 2009 Bearcat 570, Bearcat 570 XT, and T570

Condition: Arctic Cat is very concerned about complying with all aspects of the SSCC certification program. Arctic Cat has always been an advocate of snowmobile safety and environmental concerns. During a recent snowmobile certification audit, the affected models listed above did not comply with the snowmobile sound emissions requirements.

Solution: In order to comply with the SSCC certification program, it is necessary for you to install the Foam Update Kit (p/n 0637-327) for all 2009 Bearcat 570, Bearcat 570 XT, and T570 models according to the instructions included in the kit.

Parts: Order an appropriate number of Foam Update Kits (p/n 0637-327) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile.

■ **NOTE:** It is required to enter the current mileage of each affected model at the time the claim is submitted.

 ATTENTION
--

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to March 17, 2010. All warranty claims directly related to this issue will not be honored after March 17, 2010, without prior approval.
--



Bulletin de Service

Date: Le 17 mars 2009

Ligne de produit: Montoneige

Numéro de bulletin: 2009-1-10

Objet: Trousse d'actualisation de mousse
(Isolement acoustique)

Modèles concernés: Tout Bearcat 570, Bearcat 570 XT et T570 de 2009

Condition:

La société Arctic Cat est très intéressée à la conformité à tous les aspects du programme de certification du SSCC (Comité de certification de la sécurité des motoneiges). La société Arctic Cat a toujours promu la sécurité des motoneiges et le respect de l'environnement. Durant une récente vérification de certification des motoneiges, les modèles affectés indiqués ci-dessus n'ont pas répondu aux exigences sur les émissions sonores des motoneiges.

Solution:

Pour se conformer au programme de certification du SSCC, il est nécessaire d'installer la Trousse d'actualisation de mousse (n/p 0637-327) sur tous les Bearcat 570, Bearcat 570 XT et T570 de 2009, en suivant les instructions incluses dans la trousse.

Pièces:

Commandez un nombre approprié des Trousses d'actualisation de mousse (n/p 0637-327) en passant par les voies de commande de pièces normales. Votre compte de pièces de concessionnaire sera facturé et ensuite crédité lors de la réception du Formulaire de demande de réclamation de garantie.

Garantie:

Une allocation de main-d'oeuvre de 0,2 h sera payée par motoneige concernée.

■ REMARQUE: Veuillez vous rappeler que lorsque vous soumettez une réclamation, de vous assurer d'inscrire le millage actuel de chaque véhicule concerné.

⚠ ATTENTION

Pour s'assurer que le travail de révision nécessaire soit complété rapidement et que ce problème peut être réglé, Arctic Cat demande que tout travail de révision soit complété avant le 17 mars 2010. Toutes réclamations de garantie directement en rapport à ce problème ne seront plus acceptées après le 17 mars 2010 sans préautorisation.