



Service Bulletin

Date: October 13, 2009

Product Line: Snowmobile

Bulletin No: 2010-1-03

Subject: Various Components

Affected Models: All 2009 Crossfire 1000 and M1000 excluding CFR models.

■ **NOTE:** Please refer to Cat Tracker to verify if a VIN is affected by this Service Bulletin.

Condition: Under certain driving conditions, such as in extremely deep snow with prolonged use of the snowmobile, excessive under-hood heat build up can occur.

Solution: Install Heat Update Kit (p/n 0637-323) that includes various heat shields, and air duct updates bringing units with stock configurations up to Arctic Cat performance standards.

Parts: Order an appropriate number of Heat Update Kits (p/n 0637-323) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.4 hr will be paid per affected snowmobile.

■ **NOTE:** It is required to enter the current mileage of each affected model at the time the claim is submitted.

 **ATTENTION**

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to October 13, 2010. All warranty claims directly related to this issue will not be honored after October 13, 2010, without prior approval.



Bulletin de Service

Date: Le 13 octobre 2009

Ligne de produit: Montoneige

Numéro de bulletin: 2010-1-03

Objet: Composants varié

Modèles concernés: Modèles Crossfire 1000 et M1000 2009 excluant des modèles CFR.

■ **REMARQUE:** SVP Verifier sur Cat Tracker si le numéro de série est affecté par ce Bulletin de service.

Condition: Sous certaines conditions de conduite, comme par exemple en utilisant une motoneige pendant une période prolongée en neige extrêmement profonde, une accumulation de chaleur extrême sous le capot peut se produire.

Solution: Installez la Trousse d'actualisation de chaleur (n/p 0637-323) qui comprend diverses actualisations du boucliers thermique et des conduits d'air rendant les configurations d'usine des unités conformes aux normes de performance d'Arctic Cat.

Pièces: Commandez un nombre approprié des Trousse d'actualisation de chaleur (n/p 0637-323) en passant par les voies de commande de pièces normales. Votre compte de pièces de concessionnaire sera facturé et ensuite crédité lors de la réception du formulaire de demande de réclamation de garantie.

Main-d'oeuvre: Une allocation de main-d'oeuvre de 0,4 h sera payée par motoneige concernée.

■ **REMARQUE:** Le kilométrage actuel de chaque modèle visé doit être indiqué au moment de soumettre la réclamation.

ATTENTION

Pour s'assurer que le travail de révision nécessaire soit complété rapidement et que ce problème peut être réglé, Arctic Cat demande que tout travail de révision soit complété avant le 13 octobre 2010. Toutes réclamations de garantie directement en rapport à ce problème ne seront plus acceptées après le 13 octobre 2010 sans préautorisation.